


** THIS IS YOUR SPARE PARTS LIST. SAVE FOR FUTURE REFERENCE, ORDER BY PART NUMBER. CURRENT PRICES WILL BE QUOTED.**


SPARE PARTS LIST

| QTY | ITEM | DESCRIPTION | ASSY/PART # |
|-----|------|----------------------------|-------------|
| 1 | 1 | STRUT ASSEMBLY | ERC-109A |
| | 2 | | |
| 1 | 3 | WHEEL YOKE ASSEMBLY | ERC-105A |
| 2 | 4 | CLEVIS PIN | 620-012M |
| 1 | 5 | CLEVIS PIN | 150-018M |
| 3 | 6 | RETAINING RING | 1039F |
| | 7 | | |
| 1 | 8 | AXLE BAG ASSEMBLY | ERC-142A |
| 1 | 9 | UPPER STRUT ASSEMBLY | ERC-107A |
| 1 | 10 | OLED RAM ASSEMBLY | ERC-103A |
| 1 | 11 | SPRING PLUG | ERC-002M |
| 1 | 12 | SPRING 1 7/16" LONG | 650-026P |
| 1 | 13 | DIE SPRING | ERC-015P |
| 1 | 14 | #6-32 HEX. HD. CAP SPECIAL | ERC-010M |






906-226M

FACTORY REPAIR FEE= \$25.00 PLUS PARTS

| | | | |
|-----------|----------|---|--|
| CHK'D BY | |  | MFG. INC. 625 N. 12TH ST. ST. CHARLES, IL (630)584-7616 |
| DRAWN BY | J. REHAK | | |
| DATE | 3/04 | TITLE | 80" ERCOUCPE ZIROLI |
| MODEL No. | ZERCOUP | | |

** THIS IS YOUR SPARE PARTS LIST. SAVE FOR FUTURE REFERENCE, ORDER BY PART NUMBER. CURRENT PRICES WILL BE QUOTED.**



SPARE PARTS LIST

| QTY | ITEM | DESCRIPTION | ASS'Y/PART # |
|-----|------|---------------------------|--------------|
| 1 | 1 | UPPER STRUT ASSEMBLY | ERC-201A |
| 1 | 2 | OLEO STRUT ASSEMBLY | ERC-202A |
| 1 | 3 | MOUNTING BLOCK | ERC-209M |
| 1 | 4 | STEERING HORN | 159-004M |
| 1 | 5 | TORQUE LINK ASSEMBLY | 620-112A |
| 1 | 6 | SPRING 4 1/4" LONG | ERC-211M |
| 1 | 7 | AXLE | 160-020M |
| 2 | 8 | CLEVIS PIN | 620-012M |
| 2 | 9 | RETAINING RING | 1039F |
| 2 | 10 | 4-40 x 1/4" PPH | 1047F |
| 1 | 11 | 10-32 x 3/8" BHMS BLACK | 1021F |
| 1 | 12 | SPRING CUP | ERC-002M |
| 1 | 13 | SPRING 3/4" LONG | 650-038P |
| 1 | 14 | INTERNAL STAR LOCK WASHER | 1126F |
| 15 | 15 | | |

CHK'D BY
 DRAWN BY J. REHAK
 DATE 3/04
 MODEL No. ZECOUPÉ



MFG. INC.
 625 N. 12TH ST.
 ST. CHARLES, IL
 (630)584-7616
 www.robot.com

FACTORY REPAIR FEE= \$25.00 PLUS PARTS

906-227M

TITLE ERCOUPÉ STEERABLE
 NOSE GEAR ASSEMBLY