



\*\* THIS IS YOUR SPARE PARTS LIST. SAVE FOR FUTURE REFERENCE, ORDER BY PART NUMBER. CURRENT PRICES WILL BE QUOTED.\*\*


## SPARE PARTS LIST

QTY	ITEM	DESCRIPTION	ASSY/PART #
1	1	STRUT WELDMENT	GB-104A
1	2	OLEO RAM WELDMENT	GB-108A
1	3	TORQUE LINK ASSEMBLY	620-112A
1	4	SPRING 4 1/2 LONG	150-019P
2	5	CLEVIS PIN	620-012M
3	6	RETAINING RING	1039F
1	7	AXLE	159-005M
2	8	#6-32 x 1/4 BHSMS	1020F
1	9	REAR BRACE ASSEMBLY	GB-107A
1	10	CLEVIS PIN	150-012M
1	11	#8-32 x 5/8" SHCS	1128F
1	12	#8-32 LOCK NUT	1124F
1	13	STRUT MOUNTING WIRE (LH)	GB-105A
1	14	STRUT MOUNTING WIRE (RH)	GB-106A



906-222M

FACTORY REPAIR FEE= \$25.00 PLUS PARTS

CHK'D BY		 MFG. INC. 625 N. 12TH ST. ST. CHARLES, IL (630)584-7616	
DRAWN BY	J. REHAK		
DATE	3/04	TITLE	GEE BEE MAIN GEAR GREAT PLAINS
MODEL No.	GPGB		